Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC **Well Operator:** DENBURY ONSHORE, LLC

Well Name: CHSU 44C-19NH 15

Field Name: CEDAR HILLS Well File #: 15561

Date Incident:7/27/2015Time Incident:02:00Facility ID Number:County:BOWMANTwp:131Rng:105Sec:19Qtr:

Location Description: Aprroximately 300 feet east of location.

Submitted By: Josh Cuppy Received By:

Contact Person: Josh Cuppy

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	2	Barrels	2	Barrels	2	barrels	
Brine	10	Barrels	10	Barrels	10	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/25/2016 Clean Up Concluded: 9/16/2015

Risk Evaluation:

None

Areal Extent:

Released fluid flowed for very small area where it was contained using a dirt berm.

Potential Environmental Impacts:

None

Action Taken or Planned:

Well was shut in. Standing fluid was recovered. Impacted area will be removed via repair. Other area flushed and recovered.

Wastes Disposal Location: Approved landfill

Agencies Involved:

Updates

Date: 7/27/2015 Status: Reviewed - Follow-up Required Author: Suess, Bill

Updated Oil Volume: 2.00 barrels

Updated Salt Water Volume: 10.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was from a pipeline that left the well pad. Follow-up is required.

Date: 8/6/2015 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:30. 74 degrees F, P. Cloudy, West wind 15-25 mph. Observed the site and took photos. The well pad is located approximately 250 yards north of 88th St, 1st turn east of 167th Avenue. It appeared that there were three locations that had been disturbed. All were on the south side of the pad, and were on slopes facing towards the pad with the vegetation grasses and alfalfa. Cropland was on uplands adjacent to the pasture strip. It appeared new soil had been placed onto disturbed areas. Two slide off dumpsters were full of excavated soil and a pile was placed on the east side of the pad with a berm and plastic lining the bottom. No further on-site followup needed unless responsible party does not provide analytical data or photos of vegetative growth.

Date: 6/14/2016 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/14/2016 at 12:26, on location. Areas indicated in previous inspection all revegetated. Slide-off dumpsters and pile have been removed. No further follow-up required at this time.